

PRODUCT BULLETIN

OBSTRUCTION LIGHTING

Technical Support
1.800.821.5825 Option 9
aton.support.obstruction@spx.com

Product: FTS 350i-2
Brand(s): Flash Technology
Effective Date: May 8, 2025
Parts Affected: 12010879
F1350200, F1350202, F1350203, F1350204
Issued By: Ivor Lewis, Product Manager – Obstruction Lighting

Product Bulletin: FTS 350i-2 Base Configuration Update

SPX AtoN is issuing this Product Bulletin to inform customers, sales, technical support, and service teams of an update to the base configuration of the FTS 350i-2 LED beacon.



FTS 350i-2 with 3 foot pigtail

Change Summary:

Based on valuable customer feedback, the FTS 350i-2 will no longer be available pre-terminated with a 50-foot pigtail. Instead, the new standard configuration includes:

- A 3-foot factory-installed pigtail
- A Junction Box (J-Box) kit included with each unit for simplified connections and grounding

- A Quick Start Guide (QSG) for easy installation

Benefits of the Updated Configuration:

1. **Simplified Installation** – The shorter pigtail is easier to manage during installation.
2. **Enhanced Grounding** – The J-Box includes an additional grounding connector, improving resistance to static electricity and ensuring reliable grounding even on painted or coated surfaces.
3. **Easier Maintenance** – If the light needs to be replaced, press-in connectors in the J-Box allow quick disconnection without disturbing existing cabling installs.

New Part Number:

The updated FTS 350i-2 is now available under part number **12010879 – FTS 350i-2 Integrated LED Beacon Kit**.

Available Options Remain Unchanged:

- Flashrate of 20 or 30 Flashes Per Minute (FPM)
- Compatibility with radar and non-radar installations
- Optional cable lengths of 0, 50, 75, or 100 feet
- Adaptor brackets to fit 13.25" mounting plates

Discontinued Part Numbers:

The following part numbers are now discontinued as a result of this change:

- F1350200
- F1350202
- F1350203
- F1350204

Effective Immediately:

This new configuration is in effect immediately and applies to all future orders of the FTS 350i-2.

Please contact our Technical Support team if you have any issues.

Call 800-821-5825, 3, 1 (Support/Obstruction)